

bit One Firmware update v. 1.5.1.1

Read this document before performing the update

The Firmware update **VERSION 1.5.1.1 DOES NOT ADD ANY ADDITIONAL FUNCTIONALITY OR OPERATIONAL BENEFIT** as compared to the previous Firmware version 1.5.0.0 / 1.5.1.0.

This new Firmware version was engineered to help with some isolated cases which were experienced due to Hardware incompatibility. The issue concerned a loss of signal on the output of the bit One when the PC used to tune the system was disconnected.

UPDATING ANY TYPE OF FIRMWARE ALWAYS INVOLVES SOME RISKS. There is always the potential for the update to fail during the transfer process; in such cases your bit One will need to be sent back to the factory for repair. If your bit One does not exhibit the problem described in the paragraph above, **UPDATING THE FIRMWARE IS COMPLETELY UNNECESSARY.** Please consider the above risk before updating. For full technical support, please visit your local authorized dealer.